

INVESTIGATION OF LATERAL VIBRATIONS IN TURBINE-GENERATOR UNIT 5 OF THE INGA 2 HYDROELECTRIC POWER PLANT

¹André Mampuya Nzita, ²Edmond Phuku Phuati, ³Robert Muanda Ngimbi, ⁴Guyh Dituba Ngoma,

⁵Nathanael Masiala Mavungu

¹Hear of Department, ²Emeritus Professor, ³Professor, ⁴Professor, ⁵Civil Engineer ¹Departement of Electromechanics, ¹President Joseph Kasa-Vubu University, Polytechnic Faculty, Boma, Democratic Republic of the Congo

^{2.3}Departement of Physics,

^{2.3}University of Kinshasa, Faculty of science and technology, Kinshasa, Democratic Republic of the Congo
⁴University of Quebec in Abitibi-Temiscamingue, School of Enginneering, Rouyn-Noranda, Canada

Abstract: The article presents a case study on the Investigation of lateral vibrations in the turbinegenerator unit 5 of the Inga 2 hydroelectric power plant in the Democratic Republic of the Congo. Lateral vibrations were experimentally determined using twelve proximity and eddycurrent probes, positioned on each measurement plane. The results were analyzed using the Dasylab and R software. Hence, it was observed that the vibration amplitudes of the upper guide bearing, lower guide bearing, and pivot/rotor exceeded acceptable or critical limit values of the international vibration standard for a rotating speed between 100-250 rpm. These excesses can lead to rotor mass imbalances, the eccentricity of the rotor axis relative to the rotation axis of the shaft, and the deformation of the coupling shaft between the upper rotor shaft and the turbine rotor shaft. Subsequently, the means and the variances of the vibration amplitudes were evaluated and compared to the reference values of the international standard. The results of the compliance analysis revealed statistically significant differences between the measured amplitudes and the reference values. Thus, it indicates deviations from international.

IndexTerms - Component,formatting,style,styling,insert.

I. INTRODUCTION

The turbine-generator unit 5 of the Inga 2 hydroelectric power plant, which was operating at a power output close to its nominal power of 162 megawatts, presented with multiple defects in its components due to overheating of the pivot. This hydroelectric unit had been in operation for 245869,02 hours without a major overhaul and had undergone a series of interventions since February 14, 2018, due to excessive overheating of the pivot. Initial investigations suggested that the excessive friction and overheating of the results were not satisfactory for a sustained period and that the excessive friction and overheating of the pivot were due to misalignment, but the results were not satisfactory for a sustained period as the overheating persisted. Additionally, other incidents, such as misalignment detections, were not resolved.

The aim of this study is to evaluate the lateral vibrations of the turbine-generator unit 5 of the Inga 2 hydroelectric power plant, following the last alignment correction intervetion on the unit through the leveling of the cone support pivot. This study was conducted both in static and dynamic conditions, where compared to the value of the amplitude according to the international standard (Yan, Z.G. et al., 2022) and under the solicitations related to hydraulic (Saravanja, D. and Grbesic, M., 2020), mechanical, and electrical phenomena that occur during water intake in the penstock, rotation of the turbine, tensioning of the alternator, coupling, and load pick-up of the unit (Mohanta, R.S. et al., 2016, Kim, J-W. et al., 2017, Bucur, D.M. et al., 2012, Bawa, M.A. et al., 2020, Zhou, J. and Chen, Y., 2018, Huang, R. et al., 2014, Shen, A. et al., 2021, Lai, X.D. et al., 2012). The study also includes a conformity analysis to determine the statistically significant difference between the measured amplitude values and the intermational standard.

IJNRD2404504

The study also includes a compliance analysis to determine statistically significant differences between the measured amplitude values and international standards. Lateral vibrations in turbine-generator groups, such as Francis turbines, play a crucial role due to their significant impact on the performance and reliability of these systems essential for electricity production. Excessive vibrations can result in premature failures of mechanical components, disrupt energy conversion, cause undesirable fluctuations in the electrical grid, and control these vibrations in order to optimize performance, improve equipment durability, and ensure reliable electricity production (Mohanta, R.S. et al., 2016; Saravanja, D. and Grbesic, M., 2020).

III. MATERIALS AND METHODS

3.1 Materials used

The materials used in this study were twelve proximity sensors with probes that were installed and disposed of on each measurement plane as follows;

Two displacement sensors near the upper guide bearing (GEN1 Y, GEN1 X).

Two sensors were placed upstream AM at (0°) and the other downstream RG at (90°) on the measurement plane 01, located 200mm above the center of the upper guide bearings.

Four sensors near the rotor-shaft turbine coupling (GEN Y, GEN X) and (GEN' Y, GEN' X).

The first two sensors (GEN Y, GEN X) were placed upstream AM at (0°) and the other downstream RG at (90°) on the measurement plane 02, located at the lower rotor bracket, where the mobile guide bearing is fixed, while the other two sensors (GEN'Y, GEN' X) were placed upstream AM at (0°) and the other downstream RG at (90°) on the measurement plane 02' located upstream of the bottom sump cradle point towards the turbine shaft.

Two displacement sensors near the lower guide bearing (TURB Y, TURB X). The two sensors were placed upstream AM at (0°) and the other downstream RG at (90°) on the measurement plane 03, located 950 mm above the center of the lower guide bearings. The actual values of radial displacements at the lower guide bearing will be deduced based on this 950 mm height.

Using four measurement planes to record lateral displacements of the shaft line using proximity probes in hydroelectric group 5 (Figure 1), namely;

Plane 01 (upper guide bearing): GEN1.

Plane 02 (Pivot/Rotor): GEN.

Plane 02' (Pivot/shaft): GEN'.

Plane 03 (lower guide bearing): TURB.



Figure 1 : Sensor location on each measurement plane (Revue ACEC, 1982)

The sensors recorded signals that were analyzed using the Dasylab software, which is a data acquisition and evaluation system using a visual programming language (Ovadia-Blechman, Z. et al, 2002; Zloto, T. et al., 2012) and Microsoft Excel, using a calculator. The signal characteristics, locations, and names of the sensors recorded are detailed in Table 3.1.

Table 3.1 : Sensor names,	locations,	and charcteritics
---------------------------	------------	-------------------

N°	Signals	Definition	Туре	Brand	Range	Channe
						1
1	Shaft disolacement in the	GEN1 X	Telemecanique	PVC 356 1716	(4-20mA)/(0-8mm)	4
	upper guide bearig following		XS4 P18AB120			
	(X)					
2	Shaft displacement inthe	GEN1 Y	Telemecanique	PVC 356 1722	(4-20mA)/(0-8mm)	5
	upper guide bearing		XS4 P18AB120			
	following(Y)					
3	Shaft displacement in the	GEN X/GEN' X	Bently Nevada	03F0034P	(7,87V)/(1mm)	0
	pivot/rotor following (X)		3300 XL 8MM			
		CENTRACED IN M	D 1 1 1	00500040		
4	Shaft displacement in the	GEN Y/GEN' Y	Bently Nevada	03F0034C	(7,87V)/(1mm)	1
	pivot/rotor following (Y)		3300 XL 8MM			
5	Shaft displacementin the	TURB X	Bently Nevada	03F0034E	(7,87V)/(1mm)	2
	lower guide bear <mark>ing</mark>					
	folowing (X)					
6	Shaft displacementin the	TURB Y	Bently Nevada	03F0034G	(7,8 <mark>7</mark> V)/(1mm)	3
	lower guide bearing		3300 XL 8MM			
	folowing (Y)					
7	Group rotation speed	REPH	Télémé <mark>can</mark> ique	PVR 37 281	(4-20mA)/(0-8mm)	6
			XS4 P <mark>18</mark> AB120	0924		

Note;

GEN1X is where the sensors are located on the upper guide bearing following X.

GEN1Y is where the sensors are located on the upper guide bearing following Y.

GENX is where the sensors are located on the pivot/rotor following X.

GENY is where the sensors are located on the pivot/rotor following Y.

TURBX is where the sensors are located on the lower guide bearing following X.

TURBX is where the sensors are located on the lower guide bearing following Y.

3.2 Method

In the context of collecting and analyzing data on the lateral vibrations of turbine generators, proximity sensors and probes are installed to measure the amplitudes. The captured signals are then transmitted by the Dasylab software. The data undergoes preprocessing to eliminate errors and outliers (Zloto, T. et al., 2012). Using the R software, a specific technique called conformity testing is applied. This test compares the amplitudes measured by the sensors and probes against established standards. Statistical analyses are used to evaluate the conformity of the measurements (Lafaya de Micheaux, P.et al., 2014). The obtained results are interpreted to determine whether the measured amplitudes comply with the established standards.

Compliance analysis is a useful method for comparing measured data with standard values in order to determine the conformity or non-conformity of the data (Polisano, K., 2018). In the referenced article, this method was used to assess the lateral vibrations of a turbine-generator unit by comparing the measured values with international standard values (Saravanja, D. and Grbesic, M., 2020) and table 2 (Yan, ZG et al., 2022) at a significance level of 5% using the R software. Through the seven start-stop cycles, dynamic vibration data was obtained, as shown in table 1;

Table 1 : Seven start-stop cycles of the turbine-generator unit 5

Date	Start-stop	Cycles
23/10/2019	Start 01/ run without injection	11h15'TU a 11h24'TU (be it 00h09')
	Start 02/ run without injection	12h57'TU a 17h18'TU (be it 04h21')
24/10/2019	Excited start 03/ run with injection	09h16'TU a 09h39'TU (be it soit 0h33')
	Excited start 04/ run with injection	13h26'TU a 17h18'TU (be it 03h52)
25/10/2019	Excited start 05/ run with injection	13h40'TU a 13h56'TU (be it 16 min)
13/11/2019	Start 06/ run without injection	10h58'TU a 16h58'TU (be it 06h00')
19/11/2019	Excited start 07/ run with injection	10h14'TU a 16h47'TU (be it 06h33')

Name	Items	Rated speed (r/min)				
		<100	100-250	250-375	375-750	
	Horizontal vibration of head cover	0,09	0,07	0,05	0,03	
	Vertical vibration of head cover	0,11	0,09	0,06	0,03	
Turbine	Vertical vibration of thrust bearing support	0,08	0,07	0,05	0,04	
	Horizontal vibration of guide bearing	0,11	0,09	0,07	0,05	
	support					
Generator	Horizontal vibration of stator frame	0,04	0,03	0,02	0,02	
	Vibration of stator core	0.3	0.03	0.03	0.03	

Table 2 : Permissible vibration values of the turbine-generator unit (double amplitude in mm)

IV. RESULTATS AND DISCUSION

4.1 Results

Measurements were taken in static and dynamic conditions of the shaft line of the hydro-generator unit, both in the upstream-downstream (AM-AV) and left bank-right bank (RD-RG) directions in the figures (figures 2 et 3) show the shaft line at two rotor positions offset by 180°.



Figure 2 : Shaft lines along the upstream-downstream axis



Figure 3 : Shaft lines along the left bank-right bank axis

Based on the two presented graphs, the following phenomena were observed in the turbine-generator unit 5 at Inga 2; Shaft fractures in top shaft-rotor and turbine shaft-rotor couplings.

Strong eccentricity of the rotor axis in relation to the axis of rotation of the shaft line.

On these graphs, only the minimum values recorded on each measurement plane are shown, in order to illustrate the most unfavorable static positions of the shaft line.

The clearances in the guide bearings also represent the maximum lateral displacements that the shaft line will be able to perform dynamically.

These graphs represent the section of the shaft line between the upper guide bearing and the turbine guide bearing (see figures 2 and 3).

These data, once the characteristic vibration frequency (1x) of the recorded vibration signals in static conditions, are as follows on the pivot/rotor : 3,15 mm for x-axis, 1,45 mm for y-axis; upper rotor : 2,5 mm for x-axis, 2,00 mm for y-axis; upper

guide bearing : 0,7 mm for x-axis, 0,55 mm for y-axis lower guide bearing : 0,85 mm for x-axis, 0,45 mm for y-axis. In trasient conditions (star, the values are presented in table (4.1) and show in figure (4) for the last two start-ups performed.

Start-up	Measurement axes	Dynamic amp Different	plitude measure PGS	ment [µm] PIVOT/ROTOR	PGI
A	Х		810	1804	1014
Acceleration	Y	01	606	2224	893
T.11.	Х	2000	810	1865	1013
Idle run	Y	200*	606	2220	890
Hot idle run	Х	198°	442	2033	840
Hot late full	Y	170	338	2066	837
Excited run	Х	192°	853	3223	1386
Excited full	Y	1)2	549	3283	1314
Hot excited	Х	191°	454	3235	1303
run	Y	171	322	3216	1314
Deceleration	Х	203°	827	1678	967
Deceleration	Y	205	597	1963	896

Table 4.1 : Summary of the second series of recordings (start-ups : 06/07)



Figure 4 : Evolution (cloud) of the overall (peak-to-peak) displacements values for the last two tart-ups (06/07)

The nomimal voltage stage in the figure 4 has a larger amplitude value compared to the rated speed stage.

The results of the compliance analysis indicated statistically significant deviations between the measured values and the standard values at a 5% significance level and a rotatinal speed of 107,1 rpm (Consortium siemens-neyrpic, 1983) of the turbinegenerator unit 5. This indicates that the lateral vibrations exceed the specified limits in the standard in tables 1, 2, 3, and 4.

Table 1 : Amplitude value of the upper guide bearing in the x direction measured and compared to the standard in mm

[Axi	PGS	Mean	Deviation	Deviation ²	Variance	Standard	Standard	ddl	t	p-value	
IJNI	RD240	4504	Iı	nternational J	ournal of Nov	el Research a	and Develop	oment (<u>ww</u>	w.ijni	<u>rd.org</u>)		f25

© 2024 IJNRD | Volume 9, Issue 4 April 2024| ISSN: 2456-4184 | IJNRD.ORG

s(x)						deviation				
1	0.81	0.7	0.11	0.01	0.04	0.2	0.07	5	7.64	0.00**
2	0.81		0.11	0.2						
3	0.44		-0.27	0.07						
4	0.85		0.15	0.02						
5	0.45		-0.25	0.06						
6	0.83		0.13	0.02						

The difference between the mean of the measured value of the upper guide bearing in the x direction is 0.7 ± 0.2 and it is highly significant compared to the standard.

Table 2 : Amplitude value of the pivot/rotor in the y direction measured and compared to the standard in mm

Axis	PIVOT	Mean	Deviation	Deviation ²	Variance	Standard	Standard	ddl	t	p-value
(x)						deviation				
1	1.80	2.31	-0.50	0.25	0.52	0.72	0.07	5	7.57	0.00**
2	1.87		-0.44	0.19						
3	2.03		-0.27	0.07						
4	3.22		0.92	0.09						
5	3.24		0.93	0.84						
6	1.68		-0.63	0.01						

The difference between the mean of the measured value of the pivot/rotor in the x direction is 2.31 ± 0.72 and it is highly significant compared to the standard.

Table 3 : Amplitude value of the lower guide bearing in the x direction measured and compared to the standard in mm

Axis	PGI	Mean	Deviation	Deviation ²	Variance	Standard	standard	ddl	t	p-value
(x)						deviation				
1	1.01	1,1	-0.07	0.01	0.04	0.21	0.07	5	11.82	0.00***
2	1.01	_	-0.07	0.01						
3	0.84		-0.25	0.06				-		
4	1.4		0.3	0.09						
5	1.30		0.22	0.05						
6	0.97		-0.12	0.01						

The difference between the mean of the measured value of the lower guide bearing in the x direction is 1.1 ± 0.21 and it is highly significant compared to the standard.

Table 4 : Amplitude value of the lower guide bearing in the y direction measured and compared to the standard in mm

Axis	PGI	Mean	Deviation	Deviationt ²	Variance	Standard	satandard	ddl	t	p-value
(y)						deviation				
1	0.89	1.02	-0.13	0.02	0.05	0.23	0.09	5	10.14	0.00**
2	0.89		-0.13	0.02						
3	0.84		-0.19	0.03						
4	1.31		0.29	0.08						
5	1.31		0.29	0.08						
6	0.89		1.02	0.02						

The difference between the mean of the measured value of the lower guide bearing in the y direction is 1.02 ± 0.23 and it is highly significant compared to the standard.

4.2 Discussion

Apart from the compliance analysis that implies comparing the measured amplitude values using the Student's t-test to the standard, the above-mentioned result is in accordance with the evaluation requirements as reported by the following researchers: (Yan ZG et al. 2022) in their study on safety operation for large hydroelectric generator units in Japan They found that the double amplitudes of horizontal vibrations (0,2 mm, 0,35 mm, 0,36 mm, and 0,65 mm) and vertical vibrations (0,29 mm, 0,3 mm, 0,89 mm, and 1 mm) significantly exceed the standard, which is 0,07 mm for horizontal amplitude and 0,09 mm for vertical amplitude, at a norminal speed of 100-250 rpm under all operating conditions. And also (Saravanja D. and Grbesic M., 2020) in their vibration testing for assessing the hydro unit condition in different operating modes in Austria observes that the results of vibration amplitude measurements and analysis of vibrations did not show a shap increase in vibration amplitudes compared to the guidelines on permissible vibrations of such rotary machines, which belong to the group of machines 3 ISO 10816 and according ISO 7919-5 to the values of relative vibrations.

Firstly, the average amplitudes of the upper guide bearing along the x-axis show a deviation of $0,7\pm0,2$ mm from the allowed standard value of 0.07 mm. This significant deviation indicates substantial non-compliance and can have implications for the overall performance of the turbine. Higher amplitudes can result in excessive friction, increased temperature, and energy inefficiency. Moreover, the average amplitudes of the pivot/rotor on the x-axis exhibit a deviation of $2,31\pm0,72$ mm from the allowed value of 0.07 mm. This substantial difference may indicate serious issues of misalignment or wear in the pivot or rotor, which can affect the stability and reliability of the turbine. The average amplitudes of the lower guide bearing along the x-axis also display a deviation of $1,1\pm0,21$ mm from the permitted value of 0,07 mm. The significant deviation may suggest precision or deformation problems in the lower guide bearing, which can influence the performance and durability of the turbine. Last but not least, the average amplitudes of the lower guide bearing along the y-axis show a deriviation of $1,02\pm0,23$ mm from the allowed value of 0,09 mm. This significant difference may reflect issues of misalignment or wear in the y-direction, which can affect the efficiency and safety of the turbine. These statistically significant deviations between the measured amplitudes and the standard values raise important concerns regarding the performance and compliance of the turbine-alternator group. These potential problems can lead to reduced energy efficiency, permeable component wear, an increased risk of failure, and safety issues.

CONCLUSION

The study revealed that the vibrations of the rotating turbine-generator unit 5 are excessively dangerous for the machine, both on the rotor side and the turbine guide bearing side and upper guide bearing side. The results of the compliance analysis show that the difference between the mean vibration amplitudes and the vibration standard values is statistically significant at a rotation speed of 107,1 rpm. It is necessary to stop the unit to perform a complete alignment of the fixed and movable components in order to restore the verticality of the turbine-generator unit axis and align the shaft line. Furthermore, the study highlighted the need to measure turbine pressure fluctuations, thermal problems, and degradation of turbine and generator elements, such as loss of elasticity in the membrane system, wear of the water wheel, bearing, and labyrinth seals, ovalization of the stator and rotor, unreliability of temperature instrumentation, and loss of sealing between the flanges and the suction cone. These issues also require urgent intervention to ensure the proper functioning and safety of the turbine-generator unit 5.

II. ACKNOWLEDGMENT

We would like to extend our sincere gratitude to the National Electricity Company of Congo (SNEL) for their invaluable support in the completion of our work at the Inga 2 hydroelectric power plant.

REFERENCES

- [1] Bawa, M.A. Tokan A. and Salisu I. 2020. Investigation of frequent failure of Francis-hydraulic turbine guide-vane shear pin of shiroro hydro-electric power station. International journal of research publications, 57(1):44-46. DOI:10.47199/JRP100571720201326.
- [2] Bucur, D.M., Dunca, G. and Calinoiu C. 2012. Experimental vibration level analysis a Francis turbine. IOP conference series : earth and environmental science, 15:1-10. DOI: 10.1088/1315/15/6/062056.
- [3] Consortium Siemens-Neyrpic. 1983.Commissioning report of turbine-generator unit 5. 2.2.
- [4] Huang, R., An, J., Luo X, Ji, B. and Xu, H.Y. 2014. Numerical simulation of pressure vibrations in a Francis turbine draft tube with air admission. Conference paper, 2-5. DOI: 10.1115/FEDSM2014-21444.
- [5] Kim, J-W., Kwak W-I., Choe, B-S., Kim, H-H., Suh, S-H. and Lee Y-B. 2017. Therotordynamic analysis of the vibration considering the hydro-electric force supported by rolling elements in 500kW Francis turbine. Journal of mechanical science and technology, 31(11):5154-5159. DOI: 10,1007/sl2206-017-1009-0.
- [6] Lafaya de Micheaux, P., Drouilhet R. and Liquet B. 2014.Software R: mastering the language of (bio) statistical analysis. Springer. 2014; 2: 1-578.
- [7] Lai, X.D., Liao, G.L., Zhu, Y., Zhang, X., Gou, Q.Q. and Zhang, W.B. 2012.Lateral vibration of hydro turbine-generator rotor with varying stiffnes of guide bearings.IOP conference series: earth and environmental science, 15:1-15. DOI: 10.1088/1755-1315/15/4/042006.
- [8] Mohanta, R.S., Chelliah, T.R., Allamsetty, S., Akula, A. and Ghosh, R. 2016.Sources of vibration and their treatment in hydro power stations-a review. Enginnering science and technology, an international journal, 1-10. DOI: <u>http://dx.doi.org/10.1016/j.jestch.2016.11.004</u>.
- [9] Ovadia-Blechman, Z., Einav, S., Zaetsky, U., Toledo, E. and Eldar, M. 2002. The area of the pressure-flow loop for assessment of arterial stenosis : a bew index. Technologiy and hearlth care, 42.
- [10] Polisano, K. 2018. Statistics courses L1-L2 level. Hal open science. France : 1-299.
- [11] Revue ACEC. 1983. The Inga II hydroelectric power plant. 1-32.
- [12] Saravanja, D. and Grbesic, M. 2020. Vibration testing for assessing the hydro unit condition in different operating modes, Proceedings of the 31st DAAAM international symposium. Published by DAAAM international. Vienne, Austria: 19-26, discussion 25. DOI: 10.2507/31st.daaam.proceedings.003.
- [13] Shen, A., Chen, Y., Zhou, J., Yang, F., Hongliang, S. and Cai, F. 2021.Hydraulic vibration and possible exciting sources analysis in a hydropower system. Applied science, 11: 5529-3. DOI: <u>https://doi.org/10.3390/app11125529</u>.
- [14] Yan, Z.G., Cui, T., Zhou, L.T., Zhi, F.L. and Wang, Z.W. 2022.Study on safety operation for large hydroelectric generator unit. IOP conference series: earth and environmental science, 15:2-4, discussion 3-4. DOI: 10.1088/1755-1315/15/2/02202.

- [15] Zhou, J. and Chen, Y. 2018.Discussion on stochastic analysis of hydraulic vibration in pressurized water diversion and hydropower systems. Water, 10:353-6. DOI:10.3390/w10040353.
- [16] Zloto, T., Pawel, P. and Prauzner, T. 2012. Analysis of signals from inductive sensors by means of the Dasylab software. Anales UMCS informatica AX XII, 1:31-37. DOI:10.2478/v10065-0005-3.

